## Approved For Release 2002/06/10 : CIA-RDP63-00313A000500130061-6

Cop	y_6	of	б
30	/ ugus	st: (	63

25X1A

MEMORANDUM FOR THE RECORD

SUBJECT : OXCART Status

## 1. OXCART Flights, 29 August:

- A. Aircraft #124: Flight #128; purpose INS training; duration 1:50 hours. INS malfunctioned.
- B. Aircraft #126: Flight #17; purpose refueling, INS, Mach 2 cruise; duration 2:44 hours; max. Mach 2.14, max. altitude 62,000 ft. Aircraft power loss to INS precluded INS operation. A total of 52,400 lbs. fuel (full load) was transferred in 12 minutes. An acceleration climb was then made to 62,000 ft. and Mach 2.14 where engine stalls were encountered and cleared by repositioning inlet bypass doors.
- G. Aircraft #127: Flight #5; purpose refueling and ARC-50; duration 1:49 hours; subsonic. 10,000 lbs. fuel was transferred. In spite of two successful range fixes on tanker, ARC-50 needs further installation refinement. This aircraft to layup for INS installation. To be rescheduled next week.

## 2. OXCART Status, 29 August:

- A. Aircraft #121 and 122: Waiting replacement engines due compressor rub/honeycomb problem.
- B. Aircraft #125: Engine replacement. Right engine control system scheduling malfunction. Left engine excessive oil consumption (over 50 hours time).

Г	
1 - 1 -	
أتسا لأستانك للمساد ذافأ	1

## Approved For Release 2002/06/10 : CIA-RDP63-00313A000500130061-6

63 25X1A Page 2

- C. Aircraft #128: Final assembly.
- D. Aircraft #129: Arrived at 1400 hours.

25X1A Aircraft Systems Division (Special Activities)

25X1A

ASD/OSA:mvp (30 Aug 63)

Distribution:

Cy 1 - AD/OSA

2 - D/TECH/OSA

364 - ASD/OSA

5 - ASD/OSA (chrono) 6 - RB/OSA